


## **Abel Current Mining Areas**






## **Environmental Update**

- Community Complaints
- No Environmental Incident reported.
- Annual Environmental Management Report



## Abel SMP/EP Area 4



 Subsidence remediation carried out on 2 x properties due to cracking



## Mining Under Blackhill & Meredith Road



- Monitoring of Blackhill Road for Panel
  28 was complete on the 30 Jan 2016
- Monitoring of Meredith Road for Panel
  30 was complete on the 10 March 2016
- Remediation works to be undertaken by the MSB

